
Specification

Model	CCA-7910WF-21
Pick up Element	1/4" Aptina 1.0MP CMOS Sensor
Effective Picture Elements (H×V)	NTSC:976(H)×494(V)
Horizontal Resolution	720 TV Line
Minimum Illumination	0.001 Lux/F1.2
S/N Ratio	More than 50dB
Scanning System	2:1 interface
Synchronous System	Internal, Negative sync.
Auto Electronic Shutter	NTSC: 1/60s~1/100,000s
Gama Characteristic	0.45
IR Distance	65 Feet (with $ \ensuremath{ $
Video Output	1Vpp, 75Ω
Auto Gain Control	Auto
Power/Current	DC12V(+/-10%)/500mA
Lens	Board Lens 3.6mm/F2.0
Dimension (in)	6.7(W) x 2.9(H) x 2.6(D)
Weight (lb)	1.1
Storage Temperature	-22°F~140°F RH95% MAX
Operating Temperature	14°F~122°F RH95% MAX

Packing List

No	Name	Model	Number
1.	Weatherproof IR Color Camera	CCA-7910WF-21	1
2.	User Guide	CCA-7910WF-21	1





CCA-7910WF-21 Color Camera


Weatherproof IR Color Camera AHD/960H Analog



NOTE Please read this guide **BEFORE** installing



BRIEF OF PRODUCT



W.PIX MASK

CAMERA RESET

Monitor Video m ▥∩¬ DC12V CCA-7910WF-21 MENU Link wire rule: RIGHT Video Power PRES DC12V Power Supply TROUBLE AND SOLUTION TROUBLESHOOTING Power Supply Check input power connections at the terminal (AC/DC input wires) ٠ Voltage Range Measure the voltage at the terminal block. The supply range is: 12VDC. ٠ Video Connection Determine if wiring polarity at "Video Connector" is correct. If ok, the problem may be with the interconnections/ splices. • Check to make sure the coax shield is not touching "ground" ٠ Ensure that the video POOR PICTURE cable is terminated with 75 ohms at each end.

CONNECTING

■ INTRODUCTION

The Crest Electronics CCA-7910WF-21 camera is based on the latest high-resolution 960H sensor and is capable of delivering a resolution of 720TVL. The Wide Dynamic Range of the sensor allows the camera to capture detailed images even in challenging lighting conditions. With built in Smart IR and OSD menu, this camera can be adjusted to suit a wide variety of needs.

Please read this instruction manual carefully to ensure proper use of the camera.

NOTICE: For best result, please read this instruction booklet prior to installing the CCA-7910WF-21 camera.

<u>_!</u>	CAUTION: RISK OF ELECTRIC. DO NOT OPEN
CAUTION	TO REDUCE THE RISK OF ELECTRIC SHOCK DO NOT REMOVE COVER OR BACK NO USER SERVICEABLE PARTS INSIDE. REFER SERVICING TO OUALIFIED SERVICE PERSONNEL.
CAUTION	CSA CERTIFIED/UL LISTED CLASS 2 POWER ADAPTORS MUST BE USED IN ORDER TO COMPLY WITH ELECTRICAL SAFETY STANDARDS.
\wedge	
<u> </u>	Note :
Pleas F	e note the camera's operating temperature is -4°F~140°